



## Case Study

### Emergency Service – Haileybury Berwick

#### Issue:

- Haileybury College, Berwick campus lost all power as a result of water damage to the main switch board caused by a large storm overnight

#### Solution:

- Macmor Electrical Contractors were in attendance within one hour of the power outage
- Within two hours the Macmor team were cleaning the unaffected sections of the switchboard and removing the damaged parts caused by the explosion
- Macmor called in two 500Kva generators, temporary switchboards and supply cables to power the sub circuits that supply power to the school
- Working through the night, Macmor reinstated power to all sub circuits
- Business resumed as normal the following morning
- Once the temporary generators were in place, Macmor designed, manufactured and delivered a new Main switch board
- Within two weeks, the temporary solution was disconnected and the new switchboard was changed over on the weekend causing no disruption to normal business activities
- The new Main switchboard was designed with the schools future power requirements in mind
- The school was grateful for the prompt and professional service provided by Macmor